Concealed sensor shower mixer – 6 V battery

B&M SKU IDI84M4-00000 | Idral code I84M4-00000

Routine care

Clean surfaces with water and soap; avoid aggressive cleaners and dry with a soft cloth.

Keep the infrared sensor window clean and free of obstructions.

Isolate the water and electrical supply before servicing. Inspect the inlet filters and use the original troubleshooting and spare-parts documents.

Replace an exhausted battery with the specified 6 V CR-P2 lithium battery. The low-battery indicator accompanies closure of the valve.

Service

Use the original manufacturer diagrams and service procedures for disassembly and replacement.

Source: Idral ISTA43-01. This summary accompanies the original manufacturer instructions supplied separately. Read the original instructions for complete safety information, model diagrams and service procedures.