Care and Maintenance

Concealed sensor shower tap – 230 V

B&M SKU IDI84N4-01000 | Idral code I84N4-01000

Routine care

Clean surfaces with water and soap; avoid aggressive cleaners and dry with a soft cloth.

Keep the infrared sensor window clean and free of obstructions.

Isolate the water and electrical supply before servicing. Inspect the inlet filters and use the original troubleshooting and spare-parts documents.

Service

Use the original manufacturer diagrams and service procedures for disassembly and replacement.

Source: Idral ISTA43-01. This summary accompanies the original manufacturer instructions supplied separately. Read the original instructions for complete safety information, model diagrams and service procedures.